

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

2020-01-10

**Fig. 1**






Fig. 2




Fig. 3




Fig. 4

570




FIG 570




FIG 571

FIG 7







FIG 8













FIG 11



21 ~~20~~ 12






FIG. 15

To Distal  
End of  
Catheter








FIG. 16

To Proximal  
End of  
Catheter












Fig. 22




Fig. 23






Fig. 24






Fig. 26

#3

FIG 27





FIG. 28

FIG 2




FIG. 29






FIGURE 30



2006120" DTB 22007



Figure ~~33~~ 33




Figure ~~34~~ 34




Figure ~~35~~ 35



2016T20-01662001




Figure ~~36~~ 36

20061207 07:10:02




Figure 37




Figure 38




Figure ~~24~~ 39






FIG. 40



372

FIG. 341



373

FIG. 442




FIG. 843




FIG. 6A

FIG. 6B






FIG. 340




FIG. 47




FIG. 340

20077510 0152200T

440  
24

30442




FIG. 449

30439




FIG. 450






FIG. 451






FIG. 8 54




FIG. 455




FIG. 556




FIG. 557






FIG. 858

206 F20" 01522001




FIG. 59




FIG. 60




FIG. 861

1030




Fig. 10a62




Fig. ~~100b~~ 63








Fig. 10e<sub>64</sub>












Figure 71







Figure 72







**Figure 73**




**Figure 74**












Figure 80




Figure 81






Figure 82




Figure 83




Figure 84

